

---

by



---

# Blaze PowerZone Connect 8 Zone Series Crestron Home Driver

---

## User Guide

---

### Product Manual

---

[PowerZone Connect 8 Zone Series Manual](#)

### Overview

---

Package name (pkg) : AVSwitch\_Blaze\_PowerZone\_8\_Zone\_IP.pkg

Version : 1.2.5.2

This module allows integration of PowerZone Connect 8 Zone Series into a Crestron Home system. The PowerZone Connect 8 Zone Series is an audio switcher with analog and S/PDIF inputs, along with virtual mixer inputs to allow the real inputs to be mixed together into a single channel, with adjustable gain levels.

The AVSwitch module in this package provides the usual audio switching, volume and mute capabilities provided by the *AV Switch* driver type.

The Platform module in this package is an optional extra, which generates 1 Extension driver for each virtual mixer channel, providing an interface to adjust the mixer input gain levels from within the Crestron Home UI.

# Features

---

This driver provides the following functionality.

- Switching
- Volume Control
- Mute Control

## Blaze Configuration

---

Prior to setting the driver up in Crestron Home ensure that the Blaze PowerZone Connect 8 Zone Series is fully configured and works correctly. Please refer to documentation provided by Blaze to setup the unit (link at top of document).

## Support

---

If you require support for this driver please fill in a support request at <https://support.janustechnology.co.uk/>

Please ensure you provide the following information.

- Driver version you are using.
- Platform you are using e.g. Crestron Home
- Firmware version of your Blaze PowerZone Connect 8 Zone Series.
- Firmware version of your Crestron system.
- A full description of the issue you are having and how to recreate the issue.

## Troubleshooting

---

- Confirm that correct IP address is entered into the IP address field
- Confirm that correct Port is entered (if required).
- Check the Blaze PowerZone Connect 8 Zone Series can be pinged from the control system controller. If the ping fails check your network configuration and cabling.
- For IP devices we recommend using a static IP address. Ensure this is done in either the device or router.

# Blaze PowerZone Connect 8 Zone Series Crestron Driver

---

## Release Notes

---

**Category:**

**Current version:** 1.2.5.2

## Changes

---

### **Date 14th Nov 2024 - Version - v1.2.5**

- New Models

### **Date 18th Sept 2024 - Version - v1.2.4**

- Updated to fix issue clashing dll with Crestron Certified drivers

### **Date 7th July 2024 - Version - v1.2.3**

- Updated Models

### **Date 12th Dec 2023 - Version - v1.2.0**

#### **Version**

- Module: Blaze\_PowerZone Connect 8 Zone Series
- Firmware: 1.5.0
- MC4 FW: 2.8000.00010
- Crestron Home Version - v3.011.0070
- Simpl Windows - 4.2500.04.00
- Device Database - 200.280.002.00
- Crestron Database - 219.05.001.00
- Simpl+ - 4.06
- Simpl+ Cross Compiler - 1.3
- Vision Tools Pro-e - 6.2.02
- Smart Graphics Version - 2.19.00.09

#### **Enhancements**

- Added dante on Some models
- Added Mixers Support

#### **Bug Fixes**

## Exceptions

- (Crestron Home) Volume Up/Down does not work due to a bug with Crestron Home

## User Impacted

- N/A

## Date 19th July 2023 - Version - v1.1.1

## Version

- Module: Blaze\_PowerZone Connect 8 Zone Series
- Firmware: 1.4.0
- MC4 FW: 2.8000.00010
- Crestron Home Version - v3.011.0070
- Simpl Windows - 4.2500.04.00
- Device Database - 200.280.002.00
- Crestron Database - 219.05.001.00
- Simpl+ - 4.06
- Simpl+ Cross Compiler - 1.3
- Vision Tools Pro-e - 6.2.02
- Smart Graphics Version - 2.19.00.09

## Enhancements

- Added support for new virtual Mix inputs
- Allow input selection for Off
- Added signals to set primary input ducking mode
- (Crestron Home) Added power on/off commands for the device
- (Crestron Home) Created new Platform+Extension drivers for adjusting mix input gain levels

## Bug Fixes

- (Crestron Home) Correctly disposed of AV Switcher module when removed

## Exceptions

- (Crestron Home) Volume Up/Down does not work due to a bug with Crestron Home

## User Impacted

- N/A

# Date 7th March 2022 - Version - v1.0.0

## Version

- Module: Blaze\_PowerZone Connect 8 Zone Series
- Firmware: 1.2.0-beta.2
- Simpl Windows: 4.18
- MC4 FW: 2.6000.00026

## Enhancements

- Initial Release

## Bug Fixes

- N/A

## Exceptions

- N/A

## User Impacted

- N/A