

## Blaze PowerZone Connect series: Firmware Version 1.3.3

The Blaze PowerZone Connect series of DSP amplifiers uses software embedded into the hardware – known as firmware. To provide the best experience possible we release updated versions of the amplifier’s firmware. After updating, you will experience upgraded functionality and improved usability in the PowerZone Control web app.

We are pleased to announce the release of Firmware Version 1.3.3. This version includes important bug fixes and improvements that enhance the functionality and stability of the device. We highly recommend that all users upgrade to Firmware Version 1.3.3 as soon as possible to take advantage of these bug fixes and improvements.

To identify the firmware version of your Blaze PowerZone Connect amplifier and the steps required to make a firmware update, please read the document “PowerZone\_Connect\_Firmware\_update\_guide.pdf” found at: [www.blaze-audio.com/support](http://www.blaze-audio.com/support)

**Updating firmware is simple and only takes 2 minutes.**

## Features & Improvements in Firmware Version 1.3.3

### Bug fixes:

- In stereo zone: change source to off - right channel still playing
- WatchDog crash when standby
- Invert button on dashpanel is not consistent with polarity
- Zone Compressor Indicator not working in mobile
- Firmware update occasionally fails when performed over WiFi
- Protocol parser does not handle carriage return
- Protocol parser error handling updated

### User improvements:

- Input clip LED threshold