

# Blaze PowerZone Connect Crestron Driver

## Release Notes

**SimplWindows Module:** PowerZone Connect

**Category:** Audio Distribution

**Current version:** 1.2.2

## Changes

Date 27th March 2024 - Version - v1.2.2

- Updated Model Name

Date 8th Jan 2024 - Version - v1.2.1

- Updated Model Name

Date 12th Dec 2023 - Version - v1.2.0

### Version

- Module: Blaze\_PowerZone Connect
- Firmware: 1.5.0
- MC4 FW: 2.8000.00010
- Crestron Home Version - v3.011.0070
- Simpl Windows - 4.2500.04.00
- Device Database - 200.280.002.00
- Crestron Database - 219.05.001.00
- Simpl+ - 4.06
- Simpl+ Cross Compiler - 1.3
- Vision Tools Pro-e - 6.2.02
- Smart Graphics Version - 2.19.00.09

## **Enhancements**

- Added dante on Some models
- Added Mixers Support

## **Bug Fixes**

## **Exceptions**

- (Crestron Home) Volume Up/Down does not work due to a bug with Crestron Home

## **User Impacted**

- N/A

Date 19th July 2023 - Version - v1.1.1

## **Version**

- Module: Blaze\_PowerZone Connect
- Firmware: 1.4.0
- MC4 FW: 2.8000.00010
- Crestron Home Version - v3.011.0070
- Simpl Windows - 4.2500.04.00
- Device Database - 200.280.002.00
- Crestron Database - 219.05.001.00
- Simpl+ - 4.06
- Simpl+ Cross Compiler - 1.3
- Vision Tools Pro-e - 6.2.02
- Smart Graphics Version - 2.19.00.09

## **Enhancements**

- Added support for new virtual Mix inputs
- Allow input selection for Off
- Added signals to set primary input ducking mode
- (Crestron Home) Added power on/off commands for the device
- (Crestron Home) Created new Platform+Extension drivers for adjusting mix input gain levels

## **Bug Fixes**

- (Crestron Home) Correctly disposed of AV Switcher module when removed

## **Exceptions**

- (Crestron Home) Volume Up/Down does not work due to a bug with Crestron Home

### **User Impacted**

- N/A

Date 27th April 2022 - Version - v1.0.2

### **Version**

- Module: Blaze\_PowerZone Connect
- Firmware: 1.2.0-beta.2
- MC4 FW: 2.6000.00026
- Crestron Home Version - v3.011.0070
- Simpl Windows - 4.18
- Device Database - 200.14000.001.00
- Crestron Database - 210.0500.001.00
- Simpl+ - 4.06
- Simpl+ Cross Compiler - 1.3
- Vision Tools Pro-e - 6.2.02
- Smart Graphics Version - 2.17.00.05

### **Enhancements**

- Internal fixes for release.

### **Bug Fixes**

- N/A

### **Exceptions**

- N/A

### **User Impacted**

- N/A

Date 11th March 2022 - Version - v1.0.1

### **Version**

- Module: Blaze\_PowerZone Connect
- Firmware: 1.2.0-beta.2

- MC4 FW: 2.6000.00026
- Crestron Home Version - v3.011.0070
- Simpl Windows - 4.18
- Device Database - 200.14000.001.00
- Crestron Database - 210.0500.001.00
- Simpl+ - 4.06
- Simpl+ Cross Compiler - 1.3
- Vision Tools Pro-e - 6.2.02
- Smart Graphics Version - 2.17.00.05

## **Enhancements**

- Crestron Home Initial Release

## **Bug Fixes**

- N/A

## **Exceptions**

- N/A

## **User Impacted**

- N/A

Date 7th March 2022 - Version - v1.0.0

## **Version**

- Module: Blaze\_PowerZone Connect
- Firmware: 1.2.0-beta.2
- Simpl Windows: 4.18
- MC4 FW: 2.6000.00026

## **Enhancements**

- Initial Release

## **Bug Fixes**

- N/A

## **Exceptions**

- N/A

### **User Impacted**

- N/A